


Click 'Set Display options' button [☑] or click Ctrl E on the keyboard, then checkbox the Joint "labels" option as shown to view joint labels. Users can then select portions of their model to relabel with or without alpha characters




Next, from the main menu use Edit>Change Labels to change the labels of the selected joints. In this example, I changed the "Item Type" to *Element Labels – Joint*, adding the Prefix 'North' with Next number 5 with an an increment of 5. Note that you can control the labeling order by direction





Next, use the Edit menu on the Interactive Name change dialogue as shown to renumber/relabel the joints as shown below right



Joints relabeled / renumbered. You can use this option to relabel frames and other parameters also

