

Program usage

Articles

Program related articles:

General articles:

Tutorials

Title	Description	Program
2D-view cutting planes	Setting the tolerance for cutting planes within 2D views such that all desired objects are displayed.	SAP2000
Cold-formed steel truss	This tutorial demonstrates the modeling of a cold-formed steel truss system.	SAP2000
Create circular openings	Circular openings may be created within area objects, and the surrounding mesh may be improved.	SAP2000
Steel-frame pipe rack	A detailed and extensive procedure which describes the modeling, analysis, and design of a 3D steel-frame pipe rack system.	SAP2000
Vibrating-machinery steel skid on piles	This tutorial demonstrates the modeling of vibrating machinery and its connection to a steel-skid structural system.	SAP2000